ADD TO CROTTON FALLS

WELL COMPLETION REPORT

6245

41 22 15 Choron PAUS

PUTNAM COUNTY DEPARTMENT OF HEALTH

73 44 32

Division of Environmental Health Services COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

		REP	ORT MUST BE	SUBMITTED	WITHIN 30 D	AYS OF WE	LL COMPLETIO	N F	987	
OWNER	Ronald Homes, Inc.			ADDRESS 230 Glenbrook Avenue, Yonkers, N.Y.1071						
LOCATION OF WELL	(No. & Street) South Lake Blvd.			(Town) (Lot Number) Mahopac						
PROPOSED USE OF WELL	ESTABLISHMENT PUBLIC INDUSTRIAL			FARM TEST WELL GAD H						
DRILLING			COMPRESSED AIR PERCUSSION		CABLE PERCUSSION		OTHER (Specify)			
CASING LENGTH (16)		24	DIAMETER (inches) WEIGHT PER FOO		I —	X THREADED WELDED		DRIVE SHOE WAS CASING GROUTED?		
YIELD BAIL			PUMPED COMPRES			HOURS G.P.M. YIELD (G.P.M.)				
A desired			ND SURFACE - STATIC(Specify feet) DURIN		G YIELD TEST (feet)	YIELD TEST (feet)		d well		
SCREEN	MAKE	da.			200	200 in feet below Land surface: 200 LENGTH OPEN TO AQUIFE				
DETAILS	SLOT SIZE		DIAMETER (Inches)	IF GRAVEL	Diameter of we gravel pack (In	rell including	GRAVEL SIZE (Inches)	FROM (feet)	TO (rest)	
FEET to F	-		FORMATION DESCRI	PTION		Sketch exact location of well with distances, to at least two permanent landmarks.				
If yield	3 200	Medi	topsoil. um hard gra depths during drilling GALLONS		1	DWELLING.				
ATE WELL COMPL	ETED	DATE OF	DED00-		50	OUTH	LAKE	BLV	D	
6-6-77		6-14-	77 WELL	DRILLER (Sig	nature)	Ebert	MMill G. INC.			